


REMARKS

Upon further review of the specification and drawings applicant has noted there is a duplication of reference numeral 47 which refers to both the tiller and a tube. The tiller has been renumbered as 47A. Also it has been noted that output shaft 35A and bearing 35B in original Fig. 5 have not been identified by number. Both the specification and drawings have been amended to correct these minor informalities. It is submitted that no new subject matter has been introduced.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Ralph A. Dowell".

Ralph A. Dowell, Reg. No 26,868

Dowell & Dowell, P.C.
Suite 406, 2111 Eisenhower Ave.
Alexandria, VA, 22314
Telephone: 703-415-2555
Fax: 703-415-2559
e-mail: dowell@dowellpc.com

IN THE DRAWINGS:

Please enter amended Figs 1,3,4 and 5 as appended.